



## CERTIFICATE OF ANALYSIS

**REPORTED TO** Black Mountain Irrigation District  
285 Gray Avenue  
KELOWNA, BC V1X 1W8

**ATTENTION** BMID Reports

**PO NUMBER**

**PROJECT** Asbestos in Water

**PROJECT INFO**

**WORK ORDER** 9021282

**RECEIVED / TEMP** 2019-02-19 14:29 / 7°C

**REPORTED** 2019-02-22 15:31

**COC NUMBER** B76335

### Introduction:

CARO Analytical Services is a testing laboratory full of smart, engaged scientists driven to make the world a safer and healthier place. Through our clients' projects we become an essential element for a better world. We employ methods conducted in accordance with recognized professional standards using accepted testing methodologies and quality control efforts. CARO is accredited by the Canadian Association for Laboratories Accreditation (CALA) to ISO 17025:2005 for specific tests listed in the scope of accreditation approved by CALA.

#### *Big Picture Sidekicks*



You know that the sample you collected after snowshoeing to site, digging 5 meters, and racing to get it on a plane so you can submit it to the lab for time sensitive results needed to make important and expensive decisions (whew) is VERY important. We know that too.

#### *We've Got Chemistry*



It's simple. We figure the more you enjoy working with our fun and engaged team members; the more likely you are to give us continued opportunities to support you.

#### *Ahead of the Curve*



Through research, regulation knowledge, and instrumentation, we are your analytical centre for the technical knowledge you need, BEFORE you need it, so you can stay up to date and in the know.


If you have any questions or concerns, please contact me at [acrump@caro.ca](mailto:acrump@caro.ca)

### Authorized By:

Alana Crump  
Client Service Representative

1-888-311-8846 | [www.caro.ca](http://www.caro.ca)

#110 4011 Viking Way Richmond, BC V6V 2K9 | #102 3677 Highway 97N Kelowna, BC V1X 5C3 | 17225 109 Avenue Edmonton, AB T5S 1H7




## TEST RESULTS

**REPORTED TO PROJECT** Black Mountain Irrigation District  
Asbestos in Water

**WORK ORDER REPORTED** 9021282  
2019-02-22 15:31

Analyte	Result	Guideline	RL	Units	Analyzed	Qualifier
<b>Stayman Rd Sample Stn. (9021282-01)   Matrix: Water   Sampled: 2019-02-19 12:45</b>						
<i>Polarized Light Microscopy Analysis</i>						
Asbestos Fibres	None Found	N/A		%	2019-02-22	
Non-Asbestos Fibres	< 1	N/A		%	2019-02-22	
Non-Fibrous Materials	> 99	N/A		%	2019-02-22	



## APPENDIX 1: SUPPORTING INFORMATION

**REPORTED TO PROJECT** Black Mountain Irrigation District  
Asbestos in Water

**WORK ORDER REPORTED** 9021282  
2019-02-22 15:31

Analysis Description	Method Ref.	Technique	Location
Asbestos in Water	In-House	N/A	Kelowna

### Glossary of Terms:

RL	Reporting Limit (default)
%	Percent
<	Less than the specified Reporting Limit (RL) - the actual RL may be higher than the default RL due to various factors
>	Greater than the specified Result

### Guidelines Referenced in this Report:

[Guidelines for Canadian Drinking Water Quality \(Health Canada, Feb 2017\)](#)

*Note: In some cases, the values displayed on the report represent the lowest guideline and are to be verified by the end user*

### General Comments:

The results in this report apply to the samples analyzed in accordance with the Chain of Custody document. This analytical report must be reproduced in its entirety. CARO is not responsible for any loss or damage resulting directly or indirectly from error or omission in the conduct of testing. Liability is limited to the cost of analysis. Samples will be disposed of 30 days after the test report has been issued unless otherwise agreed to in writing. The quality control (QC) data is available upon request